

## Summary of Facility Information in the County of Granite

**Owner Name and Address:** Fickler Oil Co Inc 725 Maverick Ln Deer Lodge MT 59722 Phone: (406) 846-3970

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2003192	Fics Kwik Six	410 E Front St	Drummond	59832	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
6 / 06 Currently in Use	3608	11/1/1988 17 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
7 / 07 Currently in Use	3609	11/1/1988 17 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
8 / 08 Currently in Use	3610	11/1/1988 17 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
9 / 09 Currently in Use	3611	11/1/1988 17 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Granite

**Owner Name and Address:** William & Margaret Parke 153 E Mullan Trl Drummond MT 59832 Phone: (406) 288-3423

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2003611	Parkes Stage Station	350 E Front St	Drummond	59832	(406) 288-3622

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently in Use	4461	6/15/1960 46 / No	Diesel 2,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>D</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	L	D			D	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
D			D	E	F	G	H	I	J	K	L																					
6 / 06 Currently in Use	1458	6/15/1960 46 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>D</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	L	D			D	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
D			D	E	F	G	H	I	J	K	L																					
7 / 07 Currently in Use	1459	6/16/1971 35 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>D</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	L	D			D	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
D			D	E	F	G	H	I	J	K	L																					
8 / 08 Currently in Use	1460	5/13/1991 15 / No	Gasoline 6,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>D</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	L	D			D	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
D			D	E	F	G	H	I	J	K	L																					
9 / 09 Currently in Use	1461	5/13/1991 15 / No	Diesel 6,000	STI-P3 Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	<table><tr><td>A</td><td>B</td><td>C</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td>D</td><td></td><td></td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr></table>	A	B	C	D	E	F	G	H	I	J	K	L	D			D	E	F	G	H	I	J	K	L	Yes Yes Yes Yes
A	B	C	D	E	F	G	H	I	J	K	L																					
D			D	E	F	G	H	I	J	K	L																					

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Granite

**Owner Name and Address:** Cenex Harvest States 4570 N Reserve St Missoula MT 59808 Phone: (406) 543-8383

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613926	Mountain West Co Op Drummond	229 Frontage Road E	Drummond	59832	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	2846	8/25/1995 10 / No	Gasoline 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	2847	8/1/1995 10 / No	Diesel 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / S3 Currently in Use	2848	8/1/1995 10 / Ye	Gasoline 14,000	Other None	Fiberglass Reinforced Plastic Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J <input checked="" type="radio"/> L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / S4 Currently in Use	2849	8/1/1995 10 / Ye	Diesel 12,000	Other None	Fiberglass Reinforced Plastic Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J <input checked="" type="radio"/> L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes
5 / S5 Currently in Use	2850	8/1/1995 10 / Ye	Diesel 14,000	Asphalt Coated or Bare Steel None	Fiberglass Reinforced Plastic Cathodically Protected	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J <input checked="" type="radio"/> L</div> <div><input checked="" type="radio"/> <input checked="" type="radio"/> E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Granite

**Owner Name and Address:** Michael H Foley Highway 1 PO Box 12 Hall MT 59837 Phone: (406) 288-3488

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2005514	Foleys Quality Service & Supply UST	MT Highway 1 PO Box 12	Hall	59837	

TankID/Alt TankID	Tag Numbe	Installed	Product	Tank Mat'l of Construction	Piping Material	Piping Type	Tank Release Detection	FR Met																								
Status		Age/AST	Capacity	Secondary Option	Secondary Option		Piping Release Detection	Spill/Overl/C																								
5 / 05 Currently in Use	1111	8/1/1994 11 / No	Gasoline 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="3">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L	Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B			D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																					
6 / 06 Currently in Use	1112	8/1/1994 11 / No	Gasoline 4,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L		Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																						
7 / 07 Currently in Use	1113	8/1/1994 11 / No	Diesel 2,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Safe Suction	<table><tr><td>A</td><td>B</td><td>C</td><td><input checked="" type="radio"/></td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td>J</td><td>K</td><td>L</td></tr><tr><td colspan="2">B</td><td>D</td><td>E</td><td>F</td><td>G</td><td>H</td><td>I</td><td><input checked="" type="radio"/></td><td>K</td><td>L</td><td></td></tr></table>	A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L	B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L		Yes Yes Yes Yes
A	B	C	<input checked="" type="radio"/>	E	F	G	H	I	J	K	L																					
B		D	E	F	G	H	I	<input checked="" type="radio"/>	K	L																						

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Granite

**Owner Name and Address:** Hi Noon Petroleum PO Box 7578 Missoula MT 59807 Phone: (406) 532-0384

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2005771	Sunshine Station 417	3830 MT Highway 1	Philipsburg	59858	(406) 859-3450

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 01 Currently in Use	1313	4/27/1983 23 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
2 / 02 Currently in Use	4516	4/27/1983 23 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes
3 / 03 Currently In Use	4517	9/20/1999 06 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C <input checked="" type="radio"/> E F G H I J K L</div> <div>B D E F <input checked="" type="radio"/> H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed

## Summary of Facility Information in the County of Granite

**Owner Name and Address:** Bill Antonioli PO Box 486 Philipsburg MT 59858 Phone: (406) 859-3164

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613983	Pintler Petroleum Inc	906 W Broadway Road	Philipsburg	59858	(406) 859-3164

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / S1 Currently In Use	4215	9/1/2000 05 / Ye	Gasoline 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
2 / S2 Currently In Use	4216	9/1/2000 05 / Ye	Diesel 12,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
3 / S3 Currently In Use	4217	9/1/2000 05 / Ye	Gasoline 20,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes
4 / S4 Currently In Use	4218	9/1/2000 05 / Ye	Diesel 24,000	Unknown None	Flexible Plastic Double-Walled	Pressurized	<div> <div>A B C D E F G H I J K L</div> <div>B D E F G H I J K L</div> </div>	Yes Yes Yes Yes

### Tank/Piping Release Detection Codes

<b>A</b> Manual Tank Gauging	<b>C</b> Inventory Control	<b>E</b> Vapor Monitoring	<b>G</b> Interstit. Dbl-Wall Monitor	<b>I</b> SIR	<b>K</b> Deferred
<b>B</b> Tank/Line Tightness Testing	<b>D</b> ATG/Auto Line LD	<b>F</b> GW Monitoring	<b>H</b> Interstit. Sec. Con. Monitor	<b>J</b> Other Methods	<b>L</b> Not Listed